

ES (Group) Ltd

Mike Stacey Ltd

Station Road Wiveliscombe Somerset TA4 2LX United Kingdom

Ended 05 giu 2014 15:53 BST

Description
Iveco Eurocargo ML75E18K Tipper, 5880cc diesel, 7,500kg Registration: WA05 JCY Mileage: 190,579 kms Tax: No V5: Yes MOT: No
Ford Transit MWB Tipper, 90 T350, TD, 2402cc Registration: ND55 BVW Mileage: 60,201 Tax: 06/14 V5: Yes MOT: 29-06-14 Dent to bonnet, dent to nearside front wing and scuff to offside front wing
Ford Transit Connect T200 L75 panel van, 1753cc Registration: HG09 NZS Mileage: 37,760 Tax: 05/14 V5: Yes MOT: 08-06-14
Ford Transit 90 T350 LWB TD panel van, 2402cc Registration: RN04 XXZ Mileage: 200,458 Tax: 12/14 V5: Yes MOT: 11-10-14 Dents to offside panels, nearside panels and nearside door
Ford Transit 100 T260 SWB panel van Registration: HJ05 ZPY Mileage: 204,903 Tax: 03/15 V5: Yes MOT: 24-03-2015 Dent to nearside door pillar. Blown fuse on starter - unable to start
Ford Transit 85 T260 SWB TD panel van, 1998cc Registration: SM04 HZE Mileage: 115,223 Tax: 11/14 V5: Yes MOT: 30-11-14 Dent to offside front wing
Ford Transit 100 T260 SWB panel van Registration: WG04 UMV Mileage:225,104 Tax: No V5: Yes MOT: 28-06-14 Dents to offside panel, nearside sliding door, damage to offside rear light cover
Ford Transit 85 T280 SwB panel van with roof rack Registration: HD04 MPE Mileage: 150,437 Tax: 12/14 V5: Yes MOT: 07-01-15 Scuff to nearside, nearside bumper and mirror missing
Ford Transit T260 SWB TD panel van with tow bar and roof rack Registration: PG03 EJU Mileage: 144,856 Tax: No V5: Yes MOT: 26-09-14
Ford Transit T260 SWB TD panel van Registration: WX52 XVA Mileage: 216,330 Tax: No V5: Yes MOT: No Nearside mirror taped
Ford Transit T280 SWB TD panel van with roof rack Registration: HK52 EWH Mileage: 208,539 Tax: 11/14 V5: Yes MOT: 01-12-14 Scuff along offside panel
Ford Transit T280 SWB TD panel van with roof rack Registration: HD52 LVJ Mileage: 176,280 Tax: 07/14 V5: Yes MOT: 13-03-14 Nearside mirror taped, dents to nearside and offside doors
Volkswagen Passat Sport 2.0 TDI diesel estate with roof rack, front and back parking sensors Registration: KM06 PYZ Mileage: 294,062 Tax: No V5: Yes MOT: No Scuff to rear bumper, offside front door does not open using external handle
Ford Mondeo Zetec TDCI 130 estate Registration: WU56 RNE Mileage: 173,403 Tax: 02/15 V5: Yes MOT: 13-11-14 Dents to nearside right panel, nearside front wing, scuffs to offside rear door and bumper

15	Ford Mondeo Ghia TDCI 155 saloon Registration: CE55 NJO Mileage: 182,434 Tax: 08/14 V5: Yes MOT: 01-09-14 Dent to nearside door, scuff to bumper, offside front door does not open using external handle
16	Ford Mondeo Zetec TDCI Registration: KL04 FMA Mileage: 241,268 Tax: 08/14 V5: Yes MOT: No Scratches to panels
17	Vauxhall Vectra LS 2.0 DTI saloon Registration: KF51 BVD Mileage: 208,289 Tax: 06/14 V5: Yes MOT: No Scratches to panels, dents to nearside wheel arches, scuff to rear bumper
18	Vauxhall Vectra LS 2.0 DTI Registration: DV51 KXH Mileage: N/A Tax: N/A V5: Yes MOT: N/A Non-runner, for spares/repairs
18A	Ford Transit 8 seater minibus, LWB, high roof Registration: NG03 ZGH Mileage: 146,372, Tax: 10/14 V5: Yes MOT: 03-08-14
18B	Ford Transit 85 T280S FWD panel van Registration: NG56 BZK Mileage: 125,165, Tax: 10/14 V5: Yes MOT: 22-09-14
18C	Vauxhall Combo van Registration: HK04 HSN Mileage: 138,000 (approx.) Tax: No V5: Yes MOT: 12-06-14 Please note - this lot is located at Feeder Road, Bristol. Please contact Josh Chivers, joshua.chivers@es-group.com for location and to arrange viewing and collection appointments.
19	Daewoo D30S, diesel ride on forklift truck, hours run: 4,202, Year: 1998, power: 44kw, Height: 3.30. Certification of Thorough Examination valid from 07/03/2015 until 07/03/2015. Some remedial action required as per certificate. NB: to be retained until midday on the final day of clearance, Friday 1[more]
20	Benford 6 Ton dumper, model: 6000, 4x4, 4-cylinder, Deautz - NB: non-runner
21	Benford 3 Ton dumper, 4x4, 3-cylinder, Year: 1998 - NB: non-runner
22	Goodwin CD100 diesel, 2-cylinder, dry prime pump, Lister engine with 2-hoses
23	David Barton Ltd, towable lighting tower, 2-cylinder, Lister Petter engine
24	Belle Premier 100XT diesel site mixer
25	Forklift mountable sand scoop
26	Bradbury 4-post balcony D.P vehicle lift, 3 Ton, 5m approx. (NB: No Certification of Thorough Examination available. Not fit for use, sold with all faults. Equipment must be fully tested in accordance with the Loler Regulations prior to it being put into use) (NB: purchaser to supply a Risk Ass[more]
27	Britweld BR375T, 3-phase mig welder with BR802 2-roll wire feed (excluding bottle)
28	Axminster pillar drill, model: CH18F, 16-speed, Year: 1991, serial no: 305380, single phase
29	Motori Electrici steel cut off saw, swivel base, 3-phase
30	Wolf twin end bench grinder on stand, type: 0726, single phase
24	Havankill Wadanan 200 44km madali Handa CV240 matasi 440 (040), mananatan

Haverhill Wedagen 200, 11hp, model: Honda GX340, petrol, 110v/240v generator

31

32	Honda 5HP GX140, concrete poker and 2-pokers
33	Cebora plasma pocket 25, single phase
34	Two oil filled unnamed arc welders, single phase
35	Freeman 150 MA arc welder, single phase with 2-masks and assorted packets of welding rods
36	Bosch mag drill, model: GBM23-2, 1150w, Unibore (magnetic drill), model: 5028, 110v
37	CP air gun, 1" drive nut gun
38	Cengar 112G T5X air saw
39	CP cold cutter chisel
40	Two air operated scabblers and two concrete pokers
41	Hitachi DH40MA drill, type: SDS Max, 110v
42	Makita SDS drill, type: HR2020
43	Four various Ford Transit jacks
44	Quantity of assorted axle stands
45	Tancye 25 Ton hydraulic bottle jack, model: Mydra Lite 1225
46	Unbadged trolley jack
47	Heavy duty trolley jack
48	Hozelock 16L sprayer and Cuprinol fence sprayer
50	Quantity of assorted cable
51	Cryton electrical tester and Blue-Point digital gas analyser
52	Assorted lights comprising approx. 10-floodlights, 5-beacons, etc.
53	Assorted vehicle spares including; brake pads, bearing kits, brake discs and shoes, etc.
54	Assorted vehicle spares including; drive belts, light clusters, replacement mirror glass, wing mirror covers, etc.

55	Assorted vehicle spares including; air, oil, diesel filters, etc.
56	Twelve assorted excavator bucket teeth (including MR1 and MR2)
57	Ten assorted excavator bucket teeth (including IMP-122-14 x6, IMP-123-14 LH&RH, 2x K2 AH)
58	Fifteen assorted excavator bucket teeth (including E25 x5, MV x6)
59	Quantity of assorted bucket pins
60	Unbadged Anvil
61	Quantity of assorted starting handles
62	Winget pedestrian plate compactor, Honda G200 engine - NB: condition unknown
63	Tecalemit waste oil canister
64	Dual bottle trolley with quantity of assorted torches, regulators / gauges and associated hoses
65	Assorted hoses
66	Miscellaneous hand tools comprising; spirit levels, spade, pickaxe, manual pumps, etc.
67	Assorted vices
69	Hydraulic hoses and fittings
70	Hand operated pumps
71	Box of miscellaneous items comprising; 110v sockets and plugs, nails, etc.
72	Unbadged 4-wheeled commercial vacuum cleaner
73	Hydraulic pallet truck, 2,000kg
74	Five various sack trucks
75	Plastic petrol pipe and hosing and quantity of oil and air filters
76	Wheelforce 1600 MK2 tyre changer and Auto 4-wheel balancer - NB: condition unknown
77	Assorted brushes and spades

79	Tyre rack and assorted tyres
80	Assorted roof racks and tube carrier
81	Two 6ft steel 2-door cabinets, 3-drawer and 4-drawer filing cabinet with contents
82	Two aluminium ladders
83	Remaining loose contents of vehicle spares store including tote bins and contents, oil and air filters, wiper blades, etc.
84	Large quantity of assorted scrap spares / repairs including; concrete saws, mixers, etc.
85	Two torque wrenches, greaser guns, threading bars, etc.
86	Two compression tester gauges - incomplete
87	Steel workbench and Record 6VS vice
88	Assorted pneumatic tools comprising; air gauges, sprayer, sander, etc.
89	Assorted pneumatic air tools
90	Miscellaneous lot comprising; ball joint splitter, valve spring compressors, pullers, nut splitter, etc.
91	Assorted van / car spares comprising; exhausts and doors, etc.
92	Two tier steel bench and vehicle spares including; grease nipples, washers, speed nuts, ceramic fuses, etc.
93	Wheelforce 1900 wheel alignment system
94	Three 4-compartment lockers with keys
95	Four bins of assorted fixings
96	Youngman P1000 aluminium mobile access platform and Speedy Room Mate 950 mobile access platform (incomplete)
97	Large quantity of aluminium scaffold tower parts to include beams, wheels, side sections, walk boards, etc.
98	Probust kerb lifter and unbadged platform sections
99	Flymo electric lawnmower, model: E300 - no power cable
100	Six tread aluminium A-frame foldable ladder

101	Filing cabinet with contents of battery powered road traffic beacons, etc.
103	Metabo hammer drill, 110v
104	Hilti TE56 rotary hammer drill and case, 110v
105	Performance Power cordless drill with battery, charger and case
106	C.A.T cable avoidance tool
107	Five assorted measuring beam tripods and six assorted measuring staffs
108	Assorted bucket teeth and pins
109	Assorted gate hinges
110	Drop post and 3-various trailer hitch locks
111	Seven assorted fire extinguisher trolleys
112	Five assorted fire extinguisher trolleys
114	Unbadged heavy duty hydraulic concrete hammer attachment
115	Pallet of six various site transformers and distribution boxes
116	Six tread aluminium step ladder and ladder stand-off
117	Two sets of manhole cover lifters and threaded bolts
120	Three filing cabinets, kettle and 2-microwaves
124	Quantity of trench / pit prop acros
125	Large quantity of assorted acro props and shutter beam holders
126	Large quantity of assorted road signs and steel frames
127	Mobile blockbuster - hand operated
128	Eight galvanized racking feet protectors
129	Two various site vacuum cleaners

130	Large quantity of assorted 110v site lights
131	Brendon Lister Petter diesel pressure washer - NB: condition unknown
132	Bosch heavy duty breaker, 110v with trolley
133	Matebo UHE28 multi hammer drill, 110v with case
134	Assorted Hilti coring drill bits
135	One, 2 and 3-port 110v transformers, splitter box and extension reels
136	Munters fume extractor, 110v
137	Bosch 9" angle grinder, model: GWS20-230, 110v with carry case
138	Tsunami submersible water pump with hose
139	Two mobile air conditioner units, 240v
140	Two easy floats with handles and 4-brushes
141	Quantity of site / festoon lights and 110v and 240v site extension cables
142	Steel plated fireplace hood
143	Stainless steel boot wash station
144	Five 20' zip wall plasterboard sheet extension poles
145	Loose contents of store room comprising; cabling (240v, armoured), 110v and 240v connectors, assorted light bulbs and 3-drawer filing cabinet
146	Quantity of assorted fire extinguishers (NB: not certified, out of date) and fire box
147	Two bays (top shelf) of assorted sanitary ware comprising hand dryers, paper towel dispensers, plastic cisterns, ceramic pedestals / sinks, etc.
150	Rack and contents of lead / plastic cavity trays and wall ties
151	Two bays of assorted wall and floor tiles - NB: excluding racking
152	Two plastic "stop" / "go" signs
153	Bucket of assorted builders hand tools including brick hods and rakes

154	Quantity of joist hangers and wall ties
156	Pair of heavy duty ratchet adjustable cable reel jacks
158	Remaining loose contents of lean-to store comprising; hoses, building spares, M16 x 240 hexagonal anchor bolts, etc.
159	Skid mounted tipping skip
160	Skid mounted tipping skip
161	Skid mounted tipping skip
162	Skid mounted tipping skip
163	Steel storage container, 8' x 10' - NB: buyer to remove all contents (NB: purchaser to supply a Risk Assessment and Method Statement to auctioneer for approval prior to removal)
164	Steel storage container, 8' x 10' - NB: buyer to remove all contents (NB: purchaser to supply a Risk Assessment and Method Statement to auctioneer for approval prior to removal)
165	Steel storage container, 8' x 10' - NB: buyer to remove all contents (NB: purchaser to supply a Risk Assessment and Method Statement to auctioneer for approval prior to removal)
166	Site container office (NB: purchaser to supply a Risk Assessment and Method Statement to auctioneer for approval prior to removal)
167	Six road plates, various sizes
168	Nine assorted wheelbarrows in various states of repair
169	Gabion baskets and mortar bin
170	8-yard skip and scrap metal contents
171	Approximately 20 pedestrian barriers with feet
173	Approximately 3 sets of rubble chutes
174	Approximately twenty road cones
175	Quantity of chapter eight road safety barriers
176	Various steel work trestles
177	Four bays of scaffold racking including contents of plastic piping and drainage

178	Steel framed Perspex shelter
179	Quantity of road barriers
180	Contents of rack including ladders, pipework, etc.
181	Two pallets of submersible pump hose
182	Galvanized panel gate, approximately 10ft x 6ft
183	Approximately 13 - heras fencing panels and quantity of feet
185	Bristol air compressor mounted on horizontal air receiver - NB: missing crank - for spares / repairs
200	Decorative reception desk, width to bend: 1800mm, remainder width: 1700mm, max height: 1130mm with cloth upholstered office chair, 4-drawer filing cabinet and side cabinet - NB: excluding contents and I.T equipment
201	Reception suite comprising 4-cloth upholstered chairs and low-level table
202	Brother AX-425 electric typewriter
203	Three various pedestal desks and 3-cloth upholstered chairs
204	Solid wood table
205	Four steel 4-drawer filing cabinet - NB: excluding contents
206	Four cloth upholstered reception chairs and coffee table
207	Daewoo under counter refrigerator and Sharp carousel microwave
208	Alcatel OmniPCX telephone system with 20-Alcatel telephone handsets, model: 4019(5off)/4029(15off), located throughout office block
209	Single pedestal desk, table and steel 4-drawer filing cabinet
210	Three various pedestal desks, 2-cloth upholstered office chairs, two 4-drawer filing cabinets, bookcase and 2-shelving units
211	Six drawer laminate plans chest
212	Two various desks and bookcase
213	Six assorted office chairs
214	Four various steel 4-drawer filing cabinets

215	Two pedestal desks with 2-cloth upholstered office chairs
216	Hewlett Packard Slimline Intel Core i5 personal computer with flat screen monitor, keyboard and mouse, Hewlett Packard Compaq dx2000MT personal computer and Sony compact disc player
217	Directors workstation, total length approximately 3m and leatherette upholstered office chair
218	Directors wall mounted storage units
219	Light oak effect double pedestal desk, 4-drawer filing cabinet and cloth upholstered chair
220	LG Vista Quantum digital video recorder with monitor and Tatung television with Panasonic digibox and VHS player
221	Daewoo under counter refrigerator
222	Directors workstation with armchair and 2-leatherette upholstered meeting chairs
223	Four door wooden cabinet - wall mounted
224	Two cloth upholstered chairs
225	Loose contents of office comprising; desk, 2-cloth upholstered chairs, 2-storage cabinets and 2-filing cabinets
226	Loose contents of office comprising; light oak effect desk, high-backed office chair, 2-drawer and 4-drawer steel filing cabinet - NB: excluding laptop computer
227	Loose contents of office comprising; 4-various desks, 2-various 4-drawer filing cabinets and 2-cloth upholstered chairs
228	Barrel shaped, 2-section boardroom table, max length: 3,800mm, max width: 1,530mm, height: 740mm with matching 4-door sideboard
229	Ten leatherette upholstered meeting chairs with arms
230	Loose contents of office comprising; L-shape desk, 3 - various cloth upholstered chairs and 4 - drawer filing cabinet
231	Ten drawer plans chest and draftsmen board (NB: excluding contents)
232	L-shape desk, cloth upholstered chair and bookcase
233	L-shape desk, cloth upholstered chair and bookcase
234	L-shape desk and cloth upholstered high backed office chair
235	Remaining loose contents of store comprising various nails, bolts and fixtures/fittings